09/ 978,2/3

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,829,455 B2

Page 1 of 1 : December 7, 2004

DATED INVENTOR(S) : Yasumoto et al.

> It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4,

Line 3, "photosensitive" should read -- photosensitive member --.

Line 43, "comprises" should read -- comprise --.

Line 57, "holes the" should read -- the holes --.

Line 18, "ments" should read -- ment --.

Column 19,

Line 18, "potion 10" should read -- portion 10 --.

Line 33, "driving system" should read -- driven system --.

Line 47, "this" should be deleted.

Signed and Sealed this

Seventeenth Day of May, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office